

From: Larry Visoski <[REDACTED]>

To: Je vacation <jeevacation@gmail.com>

Subject: Update

Date: Thu, 30 Jul 2015 15:29:53 +0000

The BYpass filter indicator was pooped on CSD,. Cleaning filters in UltraSound cleaner and changing oil in CSD, will re-install and run engine approx 1pm,.

I have GIV fueled and ready

Thx
Larry

Sent from my iPhone