

From: Carlos Rodriguez <[REDACTED]>

To: Jeffrey Epstein <jeevacation@gmail.com>

Cc: Richard Kahn <[REDACTED]>, Ann Rodriquez <[REDACTED]>, Stephanie Remington <[REDACTED]>

Subject:

Date: Fri, 25 Jan 2019 19:47:13 +0000

Attachments: IMG_1339.JPG; IMG_1341.JPG; IMG_1343.JPG; IMG_1344.JPG; IMG_1347.JPG; IMG_1348.JPG; IMG_1350.JPG

Greetings all, These pics are from the hull of the sportis boat once the tube was completely removed by offshore. There is some delamination in the areas were the tube adheres to the boat, these need to be repaired prior to installing the tube. Offshore has their fiberglass available to start asap, to fix this and do install, please advice.

respectfully
Carlos

----- Forwarded Message -----

From: Carlos Rodriguez <[REDACTED]>

To: "[REDACTED]" <[REDACTED]>

Sent: Friday, January 25, 2019, 03:41:18 PM AST

Subject:

Sent from my iPhone

EFTA01027919