

PHOTOS - January 19, 2011

Master Suite – Sconce temporarily mounted in electrician's area. Gary M has requested advisement on whether the amount of electrical hardware which will be seen from the side is acceptable. Holes not yet filled – plasterer person to tint plaster to match sconce's color.



Outside Tub area

Area being filled in with soil for planting




Kitchen - fans



Igala - Landscaping

Intersection "dysfunction junction" bougainvilleas





Boulders at Entry – not progress – pictures of existing work from sides (up the paths)



Ion – Master Suite foyer



Wall/planter off steps leading down from MBR – progress

