

Reefco Services, Inc.

St. Thomas, VI, 00802-6463

# Invoice

Date	Invoice #
8/5/2015	109461

<b>Bill To</b>
Little Saint James

<b>Ship To</b>

P.O. Number	Terms	Rep	Ship	Via	F.O.B.	Project
Little Saint James	Due on receipt	TG	8/6/2015			

Quantity	Item Code	Description	U/M	Price Each	Amount
4	2001	<p>Labor Air-Conditioning and Refrigeration</p> <p>Manu: Sanyo Model: Locations 1)Main Kitchen, 2)Guest Cottages, 3)Pantry</p> <p>Deep clean 3 evaporator units in guest cottages under Anna's unit. 1 in pantry. Sanyo units were moldy and needed disassembly and cleaned wwith coil cleaner and brushed out fan assembly.</p> <p>Sanyo unit in main kitchen disassembled and cleaned inside fan assembly mostly caused by cooking smoke. Clean Sanyo unit in pantry. Moldy and fan assembly needed deep cleaning.</p>		101.00	404.00

<b>Phone #</b>	<b>Fax #</b>	<b>E-mail</b>	<b>Total</b>	\$404.00
----------------	--------------	---------------	--------------	----------

		reefcoservices@gmail.com
--	--	--------------------------

# REEFCO SERVICES, INC

Marine Refrigeration & Air Conditioning  
Reverse Osmosis Desalination Systems

109461

3801 Crown Bay, Suite 210  
St. Thomas USVI 00802  
Phone/Fax: [REDACTED]  
E: reefcoservices@gmail.com

NAME/VESSEL/HIN# LSJ ISLAND		DEPT. 01	DATE Aug 5/15
CONTACT/PHONE # ANNA [REDACTED]		LOCATION LSJ ISLAND	
BRAND NAME		SERIAL #	
TECH	PAYMENT TYPE	AUTH. #	
QUANTITY	DESCRIPTION	PRICE	AMOUNT
	Deep clean 3 EVAPORATOR UNITS in Guest cottages under ANNA'S UNIT. 1 in Pantry		
3	SANYO UNITS were moldy and needed disassembly & cleaned with coil cleaner & brushed out fan assembly		
1	SANYO unit in Jeffrey's main kitchen, disassembled & cleaned inside fan assembly mostly caused by cooking smoke		
1	Cleaned Sanyo unit in Pantry. Moldy & fan assembly needed deep cleaning.		
4	HOURS TECH LABOR	101 <sup>00</sup>	404 <sup>00</sup>

SIGNATURE [REDACTED]

WE APPRECIATE YOUR BUSINESS  
[www.reefco.net](http://www.reefco.net)