

LSJE, LLC

6100 Red Hook Quarters, Suite B-3, St. Thomas, VI 00802-1348

Phone: [REDACTED] E-mail: thesaintjames.group@gmail.com

Vehicle/Equipment Accident Report

Vehicle/Equipment: Lull

Date of Incident: 12/13/18

Location of Incident: GSJ

Witness: Danny

Position: Helper (Brian)

Witness:

Position:

Description of Incident:

Broken window in delivery truck - rear

Was employee operating vehicle within proper operation procedures and following all safety regulations?

Yes

No

If No, Please Explain:

Description of Damage:

Broken rear window in delivery truck

Cost of Repair:

Insurance Claim:

Print Employee Name: Brian Bates

Employee Signature:

Date:

Supervisor Signature:

Date: